

HOME INSPECTION REPORT

Smith 032908

The Report in this Booklet should be read in its entirety.

908 917-0028 908 769-0028 NJ License # 24G100067600 Bill@RootsHomeInspection.com www.rootshomeinspection.com



Inspection Report Page 1 o f 9 5/15/2008 10:30 AM



Thank you for choosing "Roots Home Inspection". Enclosed is a copy of my findings during my visual inspection of the property. My report includes a column check off for you to scan. Detailed notes are included to explain findings. Please read this report in its entirety.

The standards used in this report are set forth by the New Jersey Department of Law and Public Safety, Division of Consumer Affairs, State Board of Professional Engineers and Land Surveyors, Home Inspection Advisory Committee, N.J.A.C 13:40-15.1 et.seq and as amended to date. This can be found at www.state.nj.us/lps/ca/pels/hilaws.pdf/. For a complete description of the scope of the inspection, please refer to the Pre-Inspection Agreement, which is part of this report.

No home inspection can guarantee that some components or systems will not wear out or break in the near future. The few hours spent on this inspection only reports the condition of the home at the time of the inspection. Some problems will only be discovered after living in the home. A home inspection looks for the more serious problems that may exist that would influence your decision to buy the house. A home inspection is not an insurance policy. If you should have any questions regarding the findings, please contact me directly. Roots Home Inspection strives to complete quality work.

Good Luck with your new purchase.

Respectfully

Bill Root NJ Lic # 24G100067600



Inspection Report Page 2 o f 9 5/15/2008 10:30 AM



Summary Report

Property Inspected		
Address of property Inspected street adresss	Time/Day/Date: Saturday/March/29/2008 3:30pm	☐ Radon ☑Termite
Client Name: Smith	Client tel Tel 732 Cell	Client e-mail

REPAIRS

Below you will find a summary of my main repair concerns as listed in the notes column of the detailed report:

- 1) R- The right chimney flashing is pulled away from the brick, needs repair to prevent water penetration and further damage ...
- 2) R There is evidence of termite activity and damage to the exterior wooded fence. Repair and treatment are needed. See full evaluation in separate report sent via email.
- 3) R There are three outlets in the Florida room with no power; needs repair by licensed electrician for safety.
- 4) R The toilet bowl in the 1st floor hallway bathroom was loose at the floor. Recommend tightening and replacing a new wax seal to prevent leaks & water damage.
- 5) R The shut off value for the furnace is leaking gas and needs repair for safety. Suggest adding the Furance system on an annual service & repair contract with PSEG or local HVAC contractor. ...
- 6) R The asphalt driveway has some cracks that should be sealed to prevent water entry & further damage. Asphalt driveway surfaces require ongoing maintenance & should be sealed every 2-4 years. ...
- 7) R The 2nd floor hallway bathroom tub drain stop is not working correctly & should be repaired or replaced



Inspection Report Page 3 o f 9 5/15/2008 10:30 AM

MAINTENANCE/NOTES

Below you will find a summary of my main maintenance suggestions and notes on items/areas inspected as listed in the notes column of the detailed report:

- 1) M-This home has a finished basement. Therefore, a visual inspection beneath the walls & ceilings, in those areas, to detect any problems, was not possible
- 2) M Suggest recaulking perimeter of the shower in the 1st floor hallway bathroom to prevent water intrusion & leaking in the future
- 3) M Recommend installing Stainless Steel wrapped clothes washer water supply hoses to reduce or eliminate the possibility of bursting. This is a maintenance issue only.
- 4) M Air Conditioning System could not be inspected/tested because it was too cold outside. The compressor unit cannot be operated when it is below 60 degrees without causing damage.



Inspection Report Page 4 o f 9 5/15/2008 10:30 AM



Inspection Detail Report

		william .			_	
Property Inspected						
Address of property Inspected street address .Clark Time/Day/Date: Saturday/Ma		rch/29/2008 3:30pm		☐ Radon ☑Termite		
Client Name: Client tel smith Tel 732 C		Tel 732 Cell	, ,		Client e-mail	
Attorn	ney		Attorney Tel Tel 908 Fa	ax 973		Attorney e-mail
Buyer	's Realtor:		Buyer's Realtor			Buyer's realtor e-mail
Client	Present ⊠Yes ⊠No		Cell 908 . Approx Age 45	Style Coloni	al Split	weather: Clear 50s
Ra	ting Key		FF - 0			
S	Serviceable/Satisfactory	The system	n, component or	area is function	onal, shows signs	of typical aging and requires maintenance
M	Marginal					uire immediate maintenance. Its condition
P	Poor	The system	n, component has	s reached the		ectancy, is defective, and/or is not
Гію	diaga	functioning	g at the time of ir	nspection. It r	equires immediate	e repair or replacement.
Fin	dings	<u> </u>		DATINO	Т	NOTEO
	EXTERIO)K		RATING S M P		NOTES
. J	Foundation			3 W P		
1) E	xterior Foundation - Concre					
	round Slope & Drainage (G	rading) Go	od			
	dscaping					
	lkways				•••	
Sidewalks: Concrete Walkways: Concrete/slate/Brick						
Porch/Patio/Deck						
	Porch Front ⊠Stoop ⊠St	eps Concre	te			
6) Patio Concrete Stoop Steps						
7)	Deck/s Rear Steps None	e/.				
8) Balcony/s - None			S M P	R - The asphal	It driveway has some cracks that should be	
Driveway Applet			sealed to preve	ent water entry & further damage. Asphalt		
9) Driveway: Asphalt					aces require ongoing maintenance & should	
Fer	nce				be sealed ever	y 2-4 years
10)	Fence Wood					
11) Retaining Walls None						
Chimney/Flue from ground w/binoculars				himney flashing is pulled away from the		
12) Chimney/s: Flashing;			further damag	epair to prevent water penetration and e		
13)	◯ Cap/s					
Roofing from ground w/binoculars						
14) Roof Material Fiberglass/Asphalt ONE Layer/s Approx Age 10to 12 Yrs Usual life exp 25 yrs						
15) Flashing Vent Pipes & Other roof penetrations						
16)	Skylights: None			11111	1	



Gutters & Leaders		
17) Gutters		
18) Down Spouts & Elbows		
19) Splash plates and extensions		
Exterior Siding	SMP	
20) Wall Covering/s:; Vinyl		
21) Soffits/Eaves/Fascia: Wood; Capped		
22) Caulking (Exterior) -		
Trindotto and Dooro		
23) Windows: Metal Vinyl		
24) 🛛 Insulated Glass		
25) Glass Panes		
26) Screens and Storm Windows; Metal		
27) Storm Door/s Metal		
28) Exterior Doors Wood		
Garage	SMP	
29) Garage Attached Detached Not Inspected		
30) Doors 🗵 Electric Opener/s 🗆 Manual Door/s		
31) 🖾 Tested for Stop & Reverse		
Exterior Miscellaneous		
32) Swimming Pool & Filter System		Not Tested/ Inspected
33) Sprinkler System		Not Tested/ Inspected
34) Security System		Not Tested/ Inspected
INTERIOR	RATING	NOTES
35) Int. Walls Sheet Rock ☐ Plaster ☐ Wood Panel		
36) Ceilings Sheet Rock ☐ Plaster ☐ Suspend tiles		
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Swood Concrete Carpets STile		
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Swood Concrete Carpets Tile 38) Linoleum Squeaky Sloped		
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Swood Concrete Carpets Tile 38) Linoleum Squeaky Sloped 39) Doors		
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Swood Concrete Carpets Tile 38) Linoleum Squeaky Sloped 39) Doors 40) Steps, Stairways and Railings		
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Swood Concrete Carpets Tile 38) Linoleum Squeaky Sloped 39) Doors		
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Swood Concrete Carpets Tile 38) Linoleum Squeaky Sloped 39) Doors 40) Steps, Stairways and Railings		
36) Ceilings		
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Wood Concrete Carpets Tile 38) Linoleum Squeaky Sloped 39) Doors 40) Steps, Stairways and Railings 41) Fireplace Damper Flue/Chimney Gas Logs		
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Wood Concrete Carpets Tile 38) Linoleum Squeaky Sloped 39) Doors 40) Steps, Stairways and Railings 41) Fireplace Damper Flue/Chimney Gas Logs Kitchen . 42) Kitchen Cabinets & Counter Tops		
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Wood Concrete Carpets Tile 38) Subject Suspend Tile 39) Doors 40) Steps, Stairways and Railings 41) Fireplace Damper Flue/Chimney Gas Logs Kitchen . 42) Kitchen Cabinets & Counter Tops 43) Kitchen Sinks Faucets 44) Kitchen Sink Sprayer 45) Kitchen Sink Trap		
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor		
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor SWood Concrete Carpets Tile 38) Subject Squeaky Sloped 39) Doors 40) Steps, Stairways and Railings 41) Fireplace Damper Flue/Chimney Gas Logs Kitchen . 42) Kitchen Cabinets & Counter Tops 43) Kitchen Sinks Faucets 44) Kitchen Sink Sprayer 45) Kitchen Sink Trap 46) Garbage Disposal - None 47) Dish Washer		
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Swood Concrete Carpets Tile 38) Subject Squeaky Sloped 39) Doors 40) Steps, Stairways and Railings 41) Fireplace Damper Flue/Chimney Gas Logs Kitchen . 42) Kitchen Cabinets & Counter Tops 43) Kitchen Sinks Faucets 44) Kitchen Sink Sprayer 45) Kitchen Sink Trap 46) Garbage Disposal - None 47) Dish Washer 48) Stove Burners	S M P	
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Wood Concrete Carpets Tile 38) Subject Squeaky Sloped 39) Doors 40) Steps, Stairways and Railings 41) Fireplace Damper Flue/Chimney Gas Logs Kitchen. 42) Kitchen Cabinets & Counter Tops 43) Kitchen Sinks Faucets 44) Kitchen Sink Sprayer 45) Kitchen Sink Trap 46) Garbage Disposal - None 47) Dish Washer 48) Stove Burners 49) Oven		
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Wood Concrete Carpets Tile 38) Subject Squeaky Sloped 39) Doors 40) Steps, Stairways and Railings 41) Fireplace Damper Flue/Chimney Gas Logs Kitchen. 42) Kitchen Cabinets & Counter Tops 43) Kitchen Sinks Faucets 44) Kitchen Sink Sprayer 45) Kitchen Sink Trap 46) Garbage Disposal - None 47) Dish Washer 48) Stove Burners 49) Oven 50) Range Hood	S M P S D D S D S	
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Wood Concrete Carpets Tile 38) Support Sloped 39) Doors 40) Steps, Stairways and Railings 41) Fireplace Damper Flue/Chimney Gas Logs Kitchen. 42) Kitchen Cabinets & Counter Tops 43) Kitchen Sinks Faucets 44) Kitchen Sink Sprayer 45) Kitchen Sink Trap 46) Garbage Disposal - None 47) Dish Washer 48) Stove Burners 49) Oven 50) Range Hood 51) Exhaust Fan		
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Swood Concrete Carpets Tile 38) Subject Squeaky Sloped 39) Doors 40) Steps, Stairways and Railings 41) Fireplace Damper Flue/Chimney Gas Logs Kitchen . 42) Kitchen Cabinets & Counter Tops 43) Kitchen Sinks Faucets 44) Kitchen Sink Sprayer 45) Kitchen Sink Trap 46) Garbage Disposal - None 47) Dish Washer 48) Stove Burners 49) Oven 50) Range Hood 51) Exhaust Fan 52) Light in Range Hood		
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Wood Concrete Squeaky Sloped 38)	S M P S I I I I I I I I I I I I I I I I I I	
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Swood Concrete Carpets Tile 38) Subject Squeaky Sloped 39) Doors 40) Steps, Stairways and Railings 41) Fireplace Damper Flue/Chimney Gas Logs Kitchen . 42) Kitchen Cabinets & Counter Tops 43) Kitchen Sinks Faucets 44) Kitchen Sink Sprayer 45) Kitchen Sink Trap 46) Garbage Disposal - None 47) Dish Washer 48) Stove Burners 49) Oven 50) Range Hood 51) Exhaust Fan 52) Light in Range Hood 53) Refrigerator 54) Refrigerator Gaskets		R. The toilet howl in the 1st floor hallway bathroom was
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Swood Concrete Carpets Tile 38) Subject Squeaky Sloped 39) Doors 40) Steps, Stairways and Railings 41) Fireplace Damper Flue/Chimney Gas Logs Kitchen 42) Kitchen Sinks Faucets 43) Kitchen Sink Sprayer 45) Kitchen Sink Trap 46) Garbage Disposal - None 47) Dish Washer 48) Stove Burners 49) Oven 50) Range Hood 51) Exhaust Fan 52) Light in Range Hood 53) Refrigerator 54) Refrigerator Gaskets	S M P S I I I I I I I I I I I I I I I I I I	R - The toilet bowl in the 1st floor hallway bathroom was loose at the floor. Recommend tightening and replacing a
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Swood Concrete Squeaky Sloped 38) Linoleum Squeaky Sloped 39) Doors 40) Steps, Stairways and Railings 41) Fireplace Damper Flue/Chimney Gas Logs Kitchen . 42) Kitchen Cabinets & Counter Tops 43) Kitchen Sinks Faucets 44) Kitchen Sink Sprayer 45) Kitchen Sink Trap 46) Garbage Disposal - None 47) Dish Washer 48) Stove Burners 49) Oven 50) Range Hood 51) Exhaust Fan 52) Light in Range Hood 53) Refrigerator Gaskets Bathroom 1st Floor Full		R - The toilet bowl in the 1st floor hallway bathroom was loose at the floor. Recommend tightening and replacing a new wax seal to prevent leaks & water damage.
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Swood Concrete Carpets Tile 38) Linoleum Squeaky Sloped 39) Doors 40) Steps, Stairways and Railings 41) Fireplace Damper Flue/Chimney Gas Logs Kitchen . 42) Kitchen Cabinets & Counter Tops 43) Kitchen Sinks Faucets 44) Kitchen Sink Sprayer 45) Kitchen Sink Trap 46) Garbage Disposal - None 47) Dish Washer 48) Stove Burners 49) Oven 50) Range Hood 51) Exhaust Fan 52) Light in Range Hood 53) Refrigerator 54) Refrigerator Gaskets Bathroom 1st Floor Full 55) Sink Faucets		loose at the floor. Recommend tightening and replacing a new wax seal to prevent leaks & water damage.
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Swood Concrete Carpets Tile 38) Linoleum Squeaky Sloped 39) Doors 40) Steps, Stairways and Railings 41) Fireplace Damper Flue/Chimney Gas Logs Kitchen. 42) Kitchen Cabinets & Counter Tops 43) Kitchen Sinks Faucets 44) Kitchen Sink Sprayer 45) Kitchen Sink Trap 46) Garbage Disposal - None 47) Dish Washer 48) Stove Burners 49) Oven 50) Range Hood 51) Exhaust Fan 52) Light in Range Hood 53) Refrigerator 54) Refrigerator Gaskets Bathroom 1st Floor Full 55) Sink Faucets 56) Sink Stopper/s	S M P S I I I I I I I I I I I I I I I I I I	loose at the floor. Recommend tightening and replacing a new wax seal to prevent leaks & water damage. M - Suggest recaulking perimeter of the shower in the 1st
36) Ceilings Sheet Rock Plaster Suspend tiles 37) Floor Swood Concrete Carpets Tile 38) Linoleum Squeaky Sloped 39) Doors 40) Steps, Stairways and Railings 41) Fireplace Damper Flue/Chimney Gas Logs Kitchen . 42) Kitchen Cabinets & Counter Tops 43) Kitchen Sinks Faucets 44) Kitchen Sink Sprayer 45) Kitchen Sink Trap 46) Garbage Disposal - None 47) Dish Washer 48) Stove Burners 49) Oven 50) Range Hood 51) Exhaust Fan 52) Light in Range Hood 53) Refrigerator 54) Refrigerator Gaskets Bathroom 1st Floor Full 55) Sink Faucets		loose at the floor. Recommend tightening and replacing a new wax seal to prevent leaks & water damage.



		1
60) 🗌 Fan 🗵 Tile		
61) 🗌 Tub 🔲 Jacuzzi Type		
62) Tub Drain Stop		
63) Shower - Faucet		
64) 🛛 Shower Head & Drain		
Bathroom 2nd Floor Full		R - The 2nd floor hallway bathroom tub drain stop is not
65) Sink Faucets		working correctly & should be repaired or replaced
66) Sink Stopper/s		
67) Sink Trap/s		
68) Toilet Mechanism/Leaks		
69) Toilet Secured to Floor		
70) 🛛 Fan 🖾 Tile		
72) Tub Drain Stop		
73) Shower - Faucet		
74) Shower Head & Drain		
Silver I sala a silan	SMP	M - Recommend installing Stainless Steel wrapped
Laundry		clothes washer water supply hoses to reduce or eliminate
,		the possibility of bursting. This is a maintenance issue
75) Plumbing Hookup for Washer		only.
76) Clothes Washer		only.
77) Clothes Dryer		
78) Clothes Dryer Vented to Outside		
Attic	SMP	
79) ATTIC ENTERED Full Flooring		
80) Ventilation Soffit Vents Roof Vents		
☐ Ridge Vents ☐ Peak Vents ☐ Windows		
81) Roof Fan Peak Fan Whole House Fan		
82) Attic Access door Insulation:		
83) Structure Sheathing Trusses Sheathing		
84) NO visible leaks		
85) Insulation 10" Apx.lch		
86)		
Basement	S M P	M -This home has a finished basement. Therefore, a
87) 🛭 Basement		visual inspection beneath the walls & ceilings, in those
	 	areas, to detect any problems, was not possible
88) Concrete Slab	<u> </u>	
89) Crawl Space:		
90) Crawl Space Insulation:		·
91) Main Support Beam/s: Wood		
92) Support Columns: Steel and Cinderblock		
93) 🛛 Joists 🖾 Joist Cross Bridge Supports		
94) Water/Moisture Dry when Inspected	 	
95)	<u> </u>	
96) Efflorescence		
97) Water proof Coating		
98) Sump Pump Pit Water in Pit Sump Pump		
99) X French Drain		
100) Dehumidifier		
, =	S M P	R - There is evidence of termite activity and damage to
Wood Destroying Insects	3 IVI F	the exterior wooded fence. Repair and treatment are
		needed. See full evaluation in separate report sent via
	-	email.
Interior Other	S M P	
101) Ceiling Fans		
102) Central Vacuum None Tested NOT Tested		
102) Contial Vacadin None [103tod [] NOT Tested		



SYSTEMS	RATING	NOTES
Heating System 103) Manufacturer Kenmore	SMP	R – The shut off value for the furnace is leaking gas and
103) Manufacturer Kenmore		needs repair for safety. Suggest adding the
Hot Air; Gas Fired; BTU'S 100,000		Furance system on an annual service & repair contract
Approx Age 10 Yrs Usual life exp 25yrs		with PSEG or local HVAC contractor
104) Vent System: S Flue Chimney Direct	МПП	
105) Asbestos in/around heating sys & ducts/pipes		
106) Furnace/A/C Filters:		
107) Thermostat/s: Automatic Digital Setback		
108) GAS/OIL Main Valve & Location: Basement		
109) Oil Tank/S** In the Ground		
110) Carbon Monoxide leaks		Not Tested – Recommend having Gas Company or Local
Tro, Carbon monoxido isano		HVAC test furnace heat exchanger for cracks/ leakage.
Air Conditioning	S M P	
111) CENTRAL A/C		M - Air Conditioning System could not be
112) Manufacturer Goodman Approx. Size 3 Tons		inspected/tested because it was too cold outside. The
Approx Age 10 Yrs Usual life exp 15 yrs		compressor unit cannot be operated when it is below 60
113) ☐ Tested ☒ Not Tested due to low outdoor temp		degrees without causing damage.
	S M P	R - There are three outlets in the Florida room with no
	3 IVI P	power; needs repair by licensed electrician for safety.
114) Murray 100 amps 110/240 Volts		
Main Panel in Basement ⊠ Circuit Breakers		
115) 🛛 Copper wire 🔲 Aluminum wire		
116) Entrance Cable Condition		
117) Service Ground grounded to waterline		
118) Multi Taps		
119) Wiring ⊠Romex wire □BX/MC wire □Conduit		
120) Knob & Tube Wiring		
121) Outlets Wiring Outlets checked were wired properly & working		
122) (GFCI) Ground Fault Circuit Interrupter Outlets		
123) □Open Grounds ☑Rev Polarity ☑Open Neutl		
ES	S M P	
Plumbing		
124) Plumbing Leaks (other than faucets/ traps)		
125) Main Service Pipe: Copper		
126) Piping Thru Home: Copper		
127) Drain Pipe Material: Galvanized; PVC		
128) Waste & Vent : Cast Iron		
129) Water Main Valve & Location: Basement		
130) Water Pressure		
131) *WELL Submerged Pump Pressure Level & Gauge 132) *Pressured Holding Tank Leaks Location - Basement		
133) *Well Water: NOT tested		
134) * Water Treatment System: Not Tested		
135) *SEWAGE DISPOSAL SYSTEM Tested Not Tested		
Ancillary Systems		
136) Carbon Monoxide Detectors		Not Tested
137) Smoke Detectors		Not Tested - Most towns check them PRIOR to closing
138) Mumidifier Summarized/off/not connected		Not Tested
Water Heater	S M P	
139) Make Type GAS Size 50 Gals		



Approx Age 05 Yrs Usual life exp 10 - 12 yrs					
140) Pressure Relief Valve Safety Extension Pipe					
- f-11:	1 TT T	A	D11-1 1.	C	

The following items are not part of this inspection of any standard Home Inspection: Awnings, Bulkheads, Central Vacuum Systems, Cutoff Valves, Docks, Exterior Hose Faucets, Fuel Storage Tanks, Grills, Hot tubs, Out Building, Whirlpools, Piping (Including water, gas, Oil, or Propane), Pool Houses, Security Systems, Sheds, Barns or storage Buildings, Sprinkler Systems, Swimming Pools & Filter systems and/ or Exterior Wiring And Lighting (including low voltage landscape)

Additional Testing						
	LEAD PAINT	☐ Not Tested				
	RADON		See separate report			
	WOOD DESTROYING INSECTS *		See separate report			

- 1) This is a visual, non-invasive home inspection. Therefore, we can not determine issues that are not visible without destroying, damaging or removing obstacles or finished area.
- 2) STORED ITEMS, OBSTRUCTIONS, CLUTTER A thorough inspection of the Attic, Basement, Garage , was not possible because some or all of the perimeter walls and/or Flooring were not visible due to furniture, heavy clutter, stored items, shelves or other blockages. Structural, water or insect damage could be present. It is important that you examine these areas during your pre-closing walk-thru inspection and report any problems immediately. A \$195. Re-inspection fee applies if you want to schedule a 2nd inspection of those areas after they are cleared and a visible inspection is possible.
- 3) MOLD & MILDEW The presence of mold, mildew or other similar materials are difficult problems to diagnose. We make no representation that any mold does or does not exist in this home. Mold & mildew etc. could be concealed behind walls, under carpets, in the attic, the basement, the crawl space or other places not readily visible during this inspection. Mold & mildew are recognized as possible health hazards.
- 4) UNDERGROUND OIL TANKS We cannot determine, with certainty, that there is no underground oil tank. We check for obvious signs of buried oil tanks, such as pipes coming through the basement wall or fill pipes in the yard. The only way to be sure there is no buried tank is to have an electronic scan done on the property. We strongly recommend a scan. It costs about \$250 and is performed by a certified company. If the owner claims to have removed a tank; you must obtain all paperwork including removal certifications and inspections to protect yourself against future problems. We do not evaluate any oil tanks, above or underground. If you know that an underground tank is present, be sure that the seller has tank insurance and have it transferred to you at or before closing. If no insurance policy exists, you should have it tested, certified and insured by a qualified company prior to closing. Also, ask at what age they will stop insuring the tank.
- 5) <u>CHIMENYS</u> Fireplace and heating flue liners are not evaluated in this inspection. We provide a tier one level inspection of the chimney only. For homes over 30 years old we recommend an inspection by a certified chimney company.





Inspection Report Page 9 o f 9 5/15/2008 10:30 AM